
DATA SHEET

OOXID

READY TO USE MICROCEMENT

JNT



Calle Benifaió 38, Guadassuar (Valencia) CP 46610 Spain Tel. +34 96 116 38 84 LUNIK

DATA SHEET



2

Step by Step	Support preparation. All surfaces must be clean, dry, level and consolidated. Apply PRIMER or PRIMERQUARTZ primer, wait at least 30 minutes. If the substrate is wet, consult with Lunik technical staff. In tiles and other coatings with joints, it will be necessary to previously cover these joints with ONEROCK and allow it to dry for a minimum of 24 hours before applying the primer.
	Apply 1 coat of ONEROCK XL/L applying some pressure with the trowel. Tool: Metal trowel
\vdash	Wait 8-12 hours Sanded with 24 or 40 grit of each layer and vacuumed from the surface.
	Mix OOXID according to the specified proportions. Apply 1 coat of OOXID applying some pressure with the trowel. Tool: Metal trowel
	Wait 6-8 hours
	For metallic effect, sand with 220 grit first, and then polish with 800-1000 grit. Subsequently aspirated from the surface. For an oxidized effect, after polishing, apply an activator and leave it to act for 8 hours.
	Application of water-based aliphatic polyurethane VARNISH W (5:1) diluted with 20%-30% water. Tool: Roller
	Wait 12 hours Sanded with 400 grit for extra smoothness (optional)
	Sealing application with VARNISH W (5:1) diluted with 10% water. Tool: Roller
	NOTE: Drying times are calculated at a temperature of 20°C and a maximum relative humidity of 60%. Adapt times to environmental conditions.
	IMPORTANT: Apply the layers with a minimum thickness, and always wait until they dry to proceed with the next step. Promote air flow for optimal drying.
7 Uvix	WWW.lunik.cc Calle Benifaió 38, Guadassuar (Valencia) CP 46610 Spain Tel. +34 96 116 38 84

LUNIK

FICHA TÉCNICA



Warnings

- \cdot Do not use the product with temperatures below 0°C and above 30°C and humidity above 80%.
- \cdot Close the container correctly after each use.
- \cdot Do not add water or additives to the product without consulting.
- \cdot Avoid the fall of solid remains in the container in case of successive use of the product.
- Always apply thin layers to ensure a good curing of the product.
- \cdot In exterior applications, avoid rain when the layers have not cured.
- \cdot The curing time of the product is 7 days although it is passable after 24 hours.

Special Precautions

In case of contact with eyes, rinse with plenty of water for 15 minutes. In case of contact with skin, wash with soap and water. Do not eat. In case of ingestion, do not induce vomiting and seek medical attention immediately. It is recommended to comply with the following measures:

- \cdot Good ventilation
- \cdot Protective glasses to avoid splashes
- \cdot Rubber gloves

Cleaning and Storage

Tools must be cleaned with water immediately after use. Once the material has hardened, it can only be removed by mechanical means.

The product must be stored in its original closed container and protected from the elements at temperatures between 10°C and 30°C, in a dry and wellventilated place, away from sources of heat and direct sunlight. The time of use is 1 year from its date of manufacture, properly preserved.



www.lunik.cc

Calle Benifaió 38, Cuadassuar (Valencia) CP 46610 Spain Tel. +34 96 116 38 84

The indications and technical data that appear in this brochure are based on our current knowledge and on the most typical uses and applications of the product and are for guidance only, and may be subject to changes and modifications without prior notice. Depending on the commissioning conditions, in which we have no participation, the specific values may suffer certain variations, as well as normal differences in manufacturing tolerances, tests carried out, etc. For this reason, our guarantee is limited solely to the quality of the product supplied.